

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



OPIC
Office of Intellectual Property
INTELLECTUEL DU CANADA



CIPO
Canadian Intellectual
Property Office

(12)(19)(CA) **Brevet-Patent**

(11)(21)(C) **2,127,191**

(22) 1994/06/30

(43) 1994/10/28

(45) 1999/11/23

(72) Shouldice, Robert B., CA


(73) Shouldice Cement Products Limited, CA

(51) Int. Cl.⁶ B41F 11/06, COMB 14/28, B28D 1/00

(54) **PIERRE ARTIFICIELLE ET METHODE ET INSTALLATION
POUR LA PRODUCTION DE CELLE-CI**

(54) **ARTIFICIAL STONE AND METHOD AND APPARATUS FOR
PRODUCING SAME**

*plus petit
tumbler.*



(57) An artificial stone having a chiseled, rough hewn look on the edges, corners and irregular faces of the product, is produced by preparing a concrete block and then fracturing it, preferably along one plane, to produce a somewhat rough face along the fracture. The fractured block is then placed into the upper end of an inclined rotating cylindrical tunnel, the tunnel having at least one and preferably two internal longitudinal ribs to unbally lift the block and then produce tumbling as the tunnel rotates, the block gradually moving along the tunnel towards a lower exit end. The multiple impacts and abrasions within the tunnel produce the desired degree of additional texturing and rounding of corners and edges, to provide the desired natural aesthetic appearance. Preferably, one or both of the angle of the tunnel and the speed of rotation are adjustable, to permit variations and optimization.



Industrie Canada Industry Canada



2127191

This invention relates to the production of an artificial stone, starting from a conventional concrete block made from a conventional concrete block manufacturing machine.

5 The manufacture of concrete or cement blocks is a well-known conventional process. However, cement blocks are generally not very appealing visually. The inventor recognized that there was a need for an artificial stone which could be produced in quantity and at reasonable cost, via a process similar to conventional cement block manufacture, but
10 with additional steps to produce an aesthetic appearance, with a strong resemblance to natural stone, i.e. with a chiselled, rough-hewn look on the edges, corners and exposed faces of the product.

The inventor first tried a number of processes, without success. The first process involved a flat skid plate on a sixty degree angle. The product bounced and rolled down the skid plate, and piled up at the bottom. This process failed to achieve the desired result.

A second process involved hammers on wheels, the
20 hammers beating the face of the product as it passed by on a conveyor belt. This also failed.

A third process used the same conveyor belt, but with percussion heads mounted on the rods of air cylinders. The percussion heads were thrust into the face of the
25 product as it passed by, activation of the percussion heads being controlled by "electric eyes" sensing the arrival and departure of the product. The cylinders were mounted at various angles to provide the appearance of random impacts. The end appearance of the product was nearly acceptable, but
30 suitable production volumes could not be achieved.

A fourth process used wheels similar to those on a paddlewheel boat, which picked up the product and dropped it on the other side. Experiments were conducted with up to four paddlewheels in line, but again the results were
35 unsatisfactory.

A fifth process involved a screen on a slight angle, to which vibrators were installed to bounce the product as it passed over the screen. This also failed. At this point, the

- 2 -

2127191




FIG. 4.




FIG. 3.

2127191




FIG. 2.

2127191




FIG. 1.

